

***BlackForest Mold***  
**PA License 009412**  
**Call Us:484-764-2203**

## **Reconstruction Service**

### REPAIR

The first step of any mold remediation is to correct the underlying moisture problem to prevent reoccurring mold growth. This step is critical; any remediation plan that does not correct the moisture problem is destined to fail. The problem may be obvious, such as a leaking pipe or a simple condensation problem. Some moisture problems however will be more difficult to locate. Our knowledge of building systems allows us to locate the underlying problem and provide you with PROPER corrective measures. Next, a decision will be made to either correct the problem yourself or allow us to correct the problem for you.